

ISO 14229 P-Code	J1939-73		Name
	SPN	FMI	
P242C	3246	4	Exhaust gas temperature sensor 2 (T2) abnormality
P242D	3246	3	
P2454	3251	4	Differential pressure sensor 1 abnormality
P2455	3251	3	
P2621	523582	4	Intake throttle lift sensor abnormality
P2622	523582	3	
P3001	3252	0	Emission deterioration
P3002	4765	0	Exhaust gas temperature sensor 0: Emergency high
P3003	3242	0	Exhaust gas temperature sensor 1: Emergency high
P3004	3246	0	Exhaust gas temperature sensor 2: Emergency high
P3006	3701	15	Excessive PM3
P3007	3701	16	Excessive PM4
P3008	3701	0	Excessive PM5
P3011	132	15	Boost pressure low
P3012	523589	17	Low coolant temperature in parked regeneration
P3013	523590	16	Parked regeneration time out
P3018	523599	0	All exhaust gas temperature sensor failure
P3023	523601	0	High exhaust gas temperature after emergency high temperature DTC
P3024	523602	0	High frequency of regeneration
P3025	523603	15	Over heat pre-caution
U0075	523547	2	CAN2 Bus off
U0076	523578	2	No communication with EGR
U0077	523604	2	CAN1 Bus off
U0081	523548	2	CAN2 frame error
U0082	523591	2	
U0083	523592	2	
U0086	523595	2	
U0087	523596	2	
U0089	523598	2	

9Y1210974ELS0114US0