


L48

VENDOR: Kubota

SECTION: ELECTRICAL SYSTEM

DIAGRAM: **B10202 SWITCH /RELAY [NEW TYPE]**

<https://www.messicks.com/ku/85440?sectionId=220619&diagramId=374679>



#	Title	Description	Part Number	Price	Stock	Job Quantity	Notes	Has Image	
10	CONTROLLER	CONTROLLER	16415-65660	\$98.89	17 in stock	1		yes	Add To Cart
20	RELAY, GLOW PLUG	RELAY GLOW	16415-65600	\$53.42	16 in stock	1		yes	Add To Cart
30	BOLT, FLANGE M6X	BOLT,FLANGE	01754-50616	\$1.51	54 in stock	2		yes	Add To Cart
40	NUT, FLANGE	NUT,FLANGE	02751-50060	\$0.53	100+ in stock	2		yes	Add To Cart
50	SWITCH, SAFETY	SWITCH,SAFETY	37150-32240	\$32.36	12 in stock	1		yes	Add To Cart
60	RELAY, STARTER	RELAY STARTER	35800-75070	\$76.75	1 in stock	1		yes	Add To Cart
70	BOLT, FLANGE M6X	BOLT,FLANGE	01754-50616	\$1.51	54 in stock	1		yes	Add To Cart

#	Title	Description	Part Number	Price	Stock	Job Quantity	Notes	Has Image	
80	NUT, FLANGE	NUT,FLANGE	02751-50060	\$0.53	100+ in stock	1		yes	Add To Cart
90	UNIT FLASHER	UNIT,FLASHER	3F240-75430	\$89.55	6 in stock	1		yes	Add To Cart
100	Horn Switch	SWITCH,COMBINATION	37410-55120		5-7 business days	1		no	
100.1	SWITCH, COMBINAT	replaces #37410-55120	T2450-55120	\$60.78	5-7 business days	1 to equal #37410-55120		no	Add To Cart
105	NUT, RING	NUT,RING	35999-12660	\$6.47	5-7 business days	1		no	Add To Cart
110	Hazard Switch	SWITCH,HAZARD	TA140-30910	\$36.90	2 in stock	1		yes	Add To Cart
120	CONTROLLER	CONTROLLER	K3511-55222	\$123.55	4 in stock	1		yes	Add To Cart
125	GASKET	GASKET	3G710-71540	\$3.11	5-7 business days	1	S/N Break. Please Call	no	Add To Cart
130	BOLT, FLANGE	BOLT,FLANGE	01754-50620	\$1.89	6 in stock	2		yes	Add To Cart
140	SEAT, SWITCH	SWITCH,SEAT	TD060-47902	\$39.18	10 in stock	1		yes	Add To Cart
150	BOLT, FLANGE	BOLT,FLANGE	01754-50612	\$1.58	68 in stock	1		yes	Add To Cart
160	RELAY, GLOW	RELAY,GLOW	T1060-33710	\$91.72	2 in stock	1		yes	Add To Cart
170	STAY	STAY RELAY	32771-30810	\$7.06	5-7 business days	1		no	Add To Cart
180	RELAY #2 (5 PRON	RELAY	36919-75030		5-7 business days	1		no	
180.1	KIT RELAY	replaces #36919-75030	H3690-75000	\$26.58	5-7 business days	1 to equal #36919-75030		no	Add To Cart
190	STAY	STAY SEAT SWITCH	32771-47290	\$15.39	5-7 business days	1	S/N Break. Please Call	no	Add To Cart
200	BOLT, FLANGE (M8	BOLT,FLANGE	01754-50816	\$2.77	18 in stock	2	S/N Break. Please Call	no	Add To Cart